



January 1, 2010

BAR CODE SCANNERS

The following discontinued products have reached their End of Service Life. Therefore, new service agreements and renewals are no longer available. Please consider a replacement product. To view the current list of Motorola bar code scanners, [click here](#).

To learn more about Motorola's new products and support services, contact an Enterprise Mobility sales or service representative. Local contact numbers can be found on: www.motorola.com/enterprise/contactus.

| Product | End of Service Life Date |
|-------------|--------------------------|
| 08H1300 | 6/1/2002 |
| 08H1301 | 6/1/2002 |
| 09840-807 | 12/31/2003 |
| 16985-100 | 12/31/2003 |
| 59457-00-00 | 12/31/2003 |
| BCM2 | 12/31/2003 |
| BCM3 | 12/31/2003 |
| BCM6 | 12/31/2003 |
| BCM8 | 12/31/2003 |
| CS2000 | 12/31/2005 |
| CSM150 | 12/31/2003 |
| DATAWAND | 12/31/2003 |
| DUET SCNR | 12/31/2003 |
| DW0X | 12/31/2003 |
| DW160 | 12/31/2003 |
| DWL1 | 12/31/2003 |
| HF2000 | 12/31/2003 |
| HMD925 | 12/31/2003 |
| IP2000 | 12/31/2003 |
| IR2000 | 12/31/2003 |
| KS32xx | 12/31/2009 |
| LC29xx | 12/31/2003 |
| LL2xx | 12/31/2003 |
| LL380 | 12/31/2003 |
| LL390 | 12/31/2003 |
| LL400 | 12/31/2003 |
| LL500 | 12/31/2004 |

| Product | End of Service Life Date |
|----------|--------------------------|
| LL701 | 12/31/2003 |
| LL720 | 12/31/2003 |
| LL746 | 12/31/2003 |
| LP1503 | 12/31/2003 |
| LP1510 | 12/31/2003 |
| LP1511 | 12/31/2003 |
| LP1512 | 12/31/2003 |
| LP1525 | 12/31/2003 |
| LP1535 | 12/31/2003 |
| LP1552 | 12/31/2004 |
| LP1553 | 12/31/2003 |
| LP1555 | 12/31/2003 |
| LP1556 | 12/31/2003 |
| LS1000 | 12/31/2003 |
| LS1004 | 12/31/2003 |
| LS1006 | 12/31/2003 |
| LS19XX | 12/1/2009 |
| LS2000 | 12/31/2003 |
| LS2000MX | 12/31/2003 |
| LS2001 | 12/31/2003 |
| LS201 | 12/31/2003 |
| LS2010 | 12/31/2003 |
| LS2010MX | 12/31/2003 |
| LS2020 | 12/31/2003 |
| LS2020MX | 12/31/2003 |
| LS2030 | 12/31/2003 |
| LS2030MX | 12/31/2003 |



MOTOROLA

| Product | End of Service Life Date |
|-----------|--------------------------|
| LS2040 | 12/31/2003 |
| LS2040MX | 12/31/2003 |
| LS2050 | 12/31/2003 |
| LS2050MX | 12/31/2003 |
| LS2080 | 12/31/2003 |
| LS2080MX | 12/31/2003 |
| LS2090MX | 12/31/2003 |
| LS2100 | 6/30/2007 |
| LS2104 | 6/30/2007 |
| LS2106 | 6/30/2007 |
| LS2108 | 6/30/2007 |
| LS2501 | 8/31/2003 |
| LS2501MX | 12/31/2003 |
| LS2502MX | 12/31/2003 |
| LS2603MX | 12/31/2003 |
| LS2920 | 12/31/2003 |
| LS2930 | 12/31/2003 |
| LS3000 | 6/30/2008 |
| LS3000ALR | 4/30/2008 |
| LS3000HV | 6/30/2007 |
| LS3000LR | 2/28/2006 |
| LS3000MX | 11/30/2006 |
| LS3000VHD | 6/30/2008 |
| LS3000XLR | 12/31/2005 |
| LS3001 | 6/4/2004 |
| LS3001MX | 3/31/2004 |
| LS3002 | 12/31/2004 |
| LS3010 | 6/6/2004 |
| LS3010HV | 12/31/2004 |
| LS3020 | 8/31/2004 |
| LS3020HV | 12/31/2005 |
| LS3030 | 1/31/2004 |
| LS3050 | 12/31/2004 |
| LS3050HV | 12/31/2004 |
| LS3070 | 12/31/2005 |
| LS3070HV | 10/31/2005 |
| LS3070XLR | 3/30/2004 |
| LS3080 | 6/10/2004 |
| LS3080HV | 12/31/2004 |
| LS3100 | 12/31/2004 |
| LS3110 | 12/31/2004 |
| LS3200 | 12/31/2005 |
| LS3210 | 12/31/2005 |
| LS3220 | 12/31/2005 |
| LS3280 | 12/31/2005 |
| LS3603 | 12/31/2005 |

| Product | End of Service Life Date |
|---------------|--------------------------|
| LS3603MX | 12/31/2005 |
| LS38 | 6/6/2003 |
| LS4804 | 12/31/2005 |
| LS4804VHD | 6/3/2009 |
| LS5000 | 12/31/2003 |
| LS5100 | 12/31/2003 |
| LS5300 | 12/31/2003 |
| LS5400 | 12/31/2003 |
| LS5500 | 12/31/2003 |
| LS600x | 9/30/2008 |
| LS600xi | 12/1/2009 |
| LS61xx | 12/31/2003 |
| LS63xx | 12/31/2003 |
| LS66xx | 12/31/2003 |
| LS6804 | 12/31/2006 |
| LS6804VHD | 12/31/2006 |
| LS7000 | 12/31/2003 |
| LS7000ST | 12/31/2003 |
| LS700x | 12/31/2003 |
| LS81xx | 12/31/2003 |
| LS8500 | 12/31/2003 |
| LS8520 | 12/31/2003 |
| LS9100 | 11/3/2008 |
| LT1700 | 12/31/2004 |
| LT1720 | 12/31/2004 |
| LT1730 | 12/31/2004 |
| LT1780 | 12/31/2004 |
| LT1800 | 1/31/2007 |
| LT1804 | 1/31/2007 |
| LT1806 | 1/31/2007 |
| LT1810 | 1/31/2007 |
| LT1820 | 1/31/2007 |
| LT1830 | 1/31/2007 |
| LT1850 | 1/31/2007 |
| LT1880 | 1/31/2007 |
| MAGELLAN SL96 | 12/31/2005 |
| MAGELLAN SL97 | 12/31/2005 |
| P300STD | 12/31/2009 |
| P304IMG | 9/6/2009 |
| P304PRO | 12/31/2009 |
| P-80489-002 | 12/31/2003 |
| P-81042-001 | 12/31/2003 |
| P-81044-000 | 12/31/2003 |
| P-81048-500 | 12/31/2003 |
| P-81137-000 | 12/31/2003 |
| P-81791-000 | 12/31/2003 |



MOTOROLA

| Product | End of Service Life Date |
|-------------|--------------------------|
| P-81915-000 | 12/31/2003 |
| P-82058-000 | 12/31/2003 |
| P-82142-000 | 12/31/2003 |
| P-82303-100 | 12/31/2003 |
| PDF1000 | 12/31/2003 |
| PDF6000 | 12/31/2003 |
| PDF620 | 12/31/2004 |
| PSC Duet | 12/31/2004 |
| PSC2280 | 12/31/2003 |
| PSC4100 | 12/31/2003 |
| PSC4102 | 12/31/2003 |
| PSC4105 | 12/31/2003 |
| PSC5300 | 12/31/2003 |
| PSC5300AR | 12/31/2003 |
| PSC5300IP | 12/31/2003 |
| PSC5310 | 12/31/2003 |
| PSC5310HP | 12/31/2003 |
| PSC5310IP | 12/31/2003 |
| PSC5312 | 12/31/2003 |
| PSC5312HP | 12/31/2003 |
| PSC5312IP | 12/31/2003 |
| PSC5313 | 12/31/2003 |
| PSC5317 | 12/31/2003 |
| PSC5317HP | 12/31/2003 |
| PSC5317IP | 12/31/2003 |
| PSC5320 | 12/31/2003 |
| PSC5320IP | 12/31/2003 |
| PSC5330 | 12/31/2003 |
| PSC5340 | 12/31/2003 |
| PSC5350 | 12/31/2003 |
| PSC5350IP | 12/31/2003 |
| PSC5360 | 12/31/2003 |
| PSC5365IP | 12/31/2003 |
| PSC5370 | 12/31/2003 |
| PSC5370IP | 12/31/2003 |
| PSC5372 | 12/31/2003 |
| PSC5380 | 12/31/2003 |
| PSC5385 | 12/31/2003 |
| PSC5390 | 12/31/2003 |
| PSM20I | 11/15/2006 |
| RL470 | 12/31/2005 |
| RL471 | 12/31/2005 |
| RS32 | 12/31/2003 |
| SL6700 | 12/31/2003 |
| SL9000 | 12/31/2003 |
| STx000 | 12/31/2003 |

| Product | End of Service Life Date |
|---------|--------------------------|
| VS400X | 9/6/2009 |
| WAND | 12/31/2003 |