



January 1, 2010

## WIRELESS INFRASTRUCTURE

The following discontinued products have reached their End of Service Life. Therefore, new service agreements and renewals are no longer available. Please consider a replacement product. To view the current list of wireless infrastructure devices, [click here](#).

To learn more about Motorola's new products and support services, contact an Enterprise Mobility sales or service representative. Local contact numbers can be found on: [www.motorola.com/enterprise/contactus](http://www.motorola.com/enterprise/contactus).

Product	End of Service Life Date
20-14938-001	12/31/2003
20-14938-002	12/31/2003
20970-301	12/31/2003
24725-001	12/31/2003
2480-EOO	12/31/2003
25071-001	12/31/2003
2741	12/31/2003
2743	12/31/2003
2800	12/31/2003
2900	12/31/2003
3850	11/30/2005
3854	1/1/2004
AIR-I/O-MS2.4DS	12/31/2003
AIR-I/O-UAP-E900DS	12/31/2003
AIR-I/O-UAP-T2.4DS	12/31/2004
AIR-I/O-UAP-T2.4FH	12/31/2003
AIR-I/O-UAP-US2.4DS	12/31/2004
AIR-I/O-WH-E802DS	12/31/2003
AIR-I/O-WH-S902FH	12/31/2003
AP1000-E	12/31/2003
AP1000-L	12/31/2003
AP1000-T	12/31/2003
AP2000	12/31/2004
AP2000-E	12/31/2003
AP2000-L	12/31/2003
AP2000-T	12/31/2003
AP2300	1/1/2004
AP2411	12/31/2005

Product	End of Service Life Date
AP2412	12/31/2005
AP3000	12/31/2003
AP3000-E	12/31/2003
AP3020	6/30/2007
AP340	12/31/2003
AP350	12/31/2003
AP3500T	12/31/2003
AP4111	5/31/2007
AP4500-E	12/31/2003
AP4500T	12/31/2003
AP4800	12/31/2003
AP4800E	12/31/2003
AP4800T	12/31/2003
AP-PS11	6/30/2009
AP-PSBIAS-T-6R-24	7/1/2009
ARLAN630	12/31/2003
BR100	12/31/2003
BR1000-E	12/31/2003
BR2000-E	12/31/2003
BR2000-T	12/31/2003
BR2040-E	12/31/2003
BR2040-T	12/31/2003
BR500-T-A00	12/31/2003
BR510-T-A1	12/31/2003
BR520-T-A1	12/31/2003
BR530-T-A2	12/31/2003
BRE101-E	12/31/2003
BRE101-T	12/31/2003



**MOTOROLA**

Product	End of Service Life Date
BRE105-E	12/31/2003
BRE105-T	12/31/2003
BRE110-E	12/31/2003
BRE110-T	12/31/2003
BRE501-E	12/31/2003
BRE505-E	12/31/2003
BRE510-E	12/31/2003
BRE510-T	12/31/2003
BRE520-T	12/31/2003
BRE530-T	12/31/2003
BRIDGE	12/31/2003
BRIDGE 500E	12/31/2003
CB2000	12/31/2007
CB2401	12/31/2003
CB3020	12/31/2004
CB3021	12/31/2006
CNT2000	12/31/2003
DATANODE	12/31/2003
DCP 88	12/31/2003
DOME	12/31/2003
DS RADIO	12/31/2003
DS210	12/31/2003
DS2410	12/31/2003
DS2410IM	12/31/2003
DS2411	12/31/2003
DS2415	12/31/2003
DS2440	12/31/2003
DS2445	12/31/2003
DS29672	12/31/2003
DS630	12/31/2009
DS631	12/31/2005
DS632	12/31/2003
DS640	12/31/2003
DS655	12/31/2003
DS671	12/31/2003
DS690	12/31/2003
EAB2401	12/31/2003
EB2401	12/31/2003
EB2402	12/31/2003
GCP100	12/31/2003
GCP1000	12/31/2003
GCP2000	12/31/2003
GCP6000	12/31/2003
GCP6100	12/31/2003
GCS BASE	12/31/2003
GCS1000DS	12/31/2003

Product	End of Service Life Date
GCS2000DS	12/31/2003
GCS2000RF	12/31/2003
GCS3000DS	12/31/2003
GCS3278	12/31/2003
GCS4000DS	12/31/2003
GCS4000RF	12/31/2003
GCS4005DS	12/31/2003
GCS4005RF	12/31/2003
GCS4100DS	12/31/2003
GCS4105DS	12/31/2003
GCS5000DS	12/31/2003
GCS5000RF	12/31/2003
GCS5100DS	12/31/2003
GCS5251	12/31/2003
GCS6000DS	12/31/2003
GCS6100DS	12/31/2003
GCSXPRESS	12/31/2003
GCSXPRESS2	12/31/2003
ISA3500	12/31/2003
ISA4500	12/31/2003
ISA4800	12/31/2003
LA24xx	12/31/2003
LA3020	12/31/2005
LA3025	11/30/2005
LA3026	5/15/2009
LA4111	12/31/2004
LA4121-10xx	12/31/2007
LA503x	12/31/2007
LM-1000	12/31/2003
LM-2000	12/31/2003
LM-2500	12/31/2003
LM4500	12/31/2003
LM4800	12/31/2003
NCA3500	12/31/2003
NCA3520	12/31/2003
NCU2060	12/31/2004
NCU2062	12/31/2004
NCU2063	12/31/2004
NCU2064	12/31/2004
NCU2070	12/31/2004
NCU2362	12/31/2004
NCU2364	12/31/2004
RFC130	12/31/2003
RFC20	12/31/2003
RFC30	12/31/2003
RFC330	12/31/2003



**MOTOROLA**

<b>Product</b>	<b>End of Service Life Date</b>
RFC396	12/31/2003
RFC40	12/31/2003
RFM3010	12/31/2003
SAB2070	12/31/2004
SB2401	12/31/2003
SB2402	12/31/2003
Tellus	12/31/2003
UC1000	12/31/2003
UC1000E	12/31/2003
UC1000S	12/31/2003
UC1001I	12/31/2003
UC2000	12/31/2003
UC2000E	12/31/2003
UC2000S	12/31/2003
UC2001I	12/31/2003
UC3000E	12/31/2003
UC3000S	12/31/2003
UC3500S	12/31/2003
UC4500E	12/31/2003
UC4500S	12/31/2003
UC4800	12/31/2003
UC4800E	12/31/2003
UC4800S	12/31/2003
WCS2000DS	12/31/2003
WCS4000DS	12/31/2003
WP2446	12/31/2003